103 The Street, Adisham, Canterbury, Kent,

CT33JP, England.

07568487894

castlecapers_bouncycastlerepairs@yahoo.com

www.bouncycastlerepairs.co.uk

Castle Capers Bouncy Castle Repairs



Report on periodical test on an inflatable

Serial No	Size		Туре		Make
CC0465	3.7m L >	(3.1m W x 2.66m H	Farm Castle		Andy J
Name and address of own	ner	Air Play			
Manufacture date		Place of inspection			Name of inspector
2019		Air Play		Philippa Miller	

Seams & stitching Blower length Inside wall height Fall off height Step/ramp	Exits Exit markings Independent support Deflation	
Inside wall height Fall off height	Independent support Deflation	
Fall off height	Deflation	
Step/ramp	Emorgona, lightin-	
	Emergency lighting	
Entrapment	Slides	
Trough depth	Platform height	
Grounding	Platform wall	
Sharp angles	1 st M wall	
Stability	Slope remainder	
Pressure	Climb	
deflation	Run out	
Air loss	End	
Markings	Slip sheet	
Identifications	Climb sheet	
Walls & towers	Run out length	
	Grounding Sharp angles Stability Pressure deflation Air loss Markings Identifications	

below

How many users to height

1 M = 5 1.2 M = 0 1.5 M = 0 1.8 M = 0

Risk assessment	Notes	
Designated entrance and exit areas should be adhered to at all	Max height = 1.25m	
times. This safety certificate is for the inflatable only.	Max users at this height = 4	

I certify that the above equipment has been tested to BSEN 14960 (if applicable) and any necessary repairs have been carried out and the equipment is now in satisfactory condition for use.

Date of inspection: 07.05.25

Expiry date: 07.05.26

