103 The Street, Adisham, Canterbury, Kent,

CT33JP, England.

07568487894

castlecapers_bouncycastlerepairs@yahoo.com

www.bouncycastlerepairs.co.uk

Castle Capers Bouncy Castle Repairs



Report on periodical test on an inflatable

Serial No	Size		Туре		Make
CC0984	5.5m L x 3.75m W x 2.95m H		3D Monster Truck Combi		Airquee
Name and address of owr	er		Air Play		
Manufacture date		Place of inspection		Name of inspector	
2023		Air Play		Philippa Miller	

Anchorage	Structure	Totally enclosed	
How Many/type	Seams & stitching	Exits	
Accessories	Blower length	Exit markings	
Blower	Inside wall height	Independent support	
Inlet, outlet mesh	Fall off height	Deflation	
Cable and socket	Step/ramp	Emergency lighting	
Impeller & flap	Entrapment	Slides	
1.5hp	Trough depth	Platform height	
PAT test	Grounding	Platform wall	
Material	Sharp angles	1 st M wall	
Fabric FR/strength	Stability	Slope remainder	
Zips	Pressure	Climb	
Thread	deflation	Run out	
Rope	Air loss	End	
Netting	Markings	Slip sheet	
Windows	Identifications	Climb sheet	
Artwork	Walls & towers	Run out length	
Il parts relevant to this u	nit have been inspected and f	ound satisfactory unless liste	

below

How many users to height

1 M = 7 1.2 M = 5 1.5 M = 4 1.8 M = 4

ght = 1.8m		
Max users at this height = 4		
at		

I certify that the above equipment has been tested to BSEN 14960 (if applicable) and any necessary repairs have been carried out and the equipment is now in satisfactory condition for use.

Date of inspection: 07.05.25

Expiry date: 07.05.26

